

JO Contractor Fatality


1. Time/Date of Accident – 9 February, 2006; 10:50 Hrs



3. Location of Incident – POD Production Yard

4. Description of Incident – Four employees of FKS contracting company were welding a flange on a piece of 12 inch pipe, 12 meters in length to be utilized in a manifold for one of the Subcenters. Three of the contract employees were inside of a tarpaulin enclosure. Two of the three were welders and one was a welders helper. The welders were completing the weld when the pipe began to move. The pipe was on pipe supports located on open ground ninety cm above the ground. The wind was blowing approximately 35+mph. When the pipe began to move the contract employees began to evacuate the tarpaulin enclosure. Two of the workers evacuated the enclosure through one exit and the deceased through another. At this time the pipe fell and struck an adjacent pipe, also on pipe stands which was parallel to the pipe being worked on, approximately one meter away. The deceased was struck by the second pipe as he apparently tried to escape by passing underneath it. He sustained injuries to his face and head and pronounced dead in by Adan hospital.


5. Situation Status – Incident is under investigation.

Initial position of two 12" pipes on pipe supports and workers welding flange on one pipe






- 1) Welders noticed Pipe – 1 started shaking and immediately moved away.
- 2) Helper in the middle of Pipe-1 and Pipe – 2 presumably tried to move away underneath Pipe-2
- 3) At this time Pipe-1 fell on Pipe-2 and as a result Pipe-2 fell on the head of the helper, fatally injuring him.



Pipe-2 fell on the head of the helper, fatally injuring him.



Pipe - 2

Deceased person's helmet

Pipe - 1

9 2 2006