

HSE Alert Burst Grinding Disk hits face shield



Another SOLID and GOOD reason for using a face shield when grinding


These pictures were taken on a job site where the incident actually happened. (Non Shell)
They were not doctored in any way but they show a very good reason for using a face shield when operating grinding equipment.

Imagine what would have happened if the worker had not had the face shield in place when the wheel shattered and broke.

If the worker had not been wearing the shield, it would have been a very serious injury with possible loss of sight depending on how it hit the face.

These pictures would be a good way to help raise the level of consciousness when using grinders as well as the other things we do that necessitate the use of face shields.

Feel free to print and use these pictures in your safety meetings and the company alerts.



Part of Grinding Disc embedded in face shield